

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/Copy Audit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Canon 2120	A1-98-47/47A	Connector built-in		
Canon 3030	A1-98-47/47A	Connector built-in		
Canon 3050	A1-98-47/47A	Connector built-in		
Canon 330	A1-98-47/47A	Connector built-in		
Canon 3725	A1-98-08	Connector built-in		
Canon 3825	A1-98-47/47A	Connector built-in		
Canon 4835s	A1-98-47/47A	Connector built-in		
Canon 5000	A1-98-47/47A	Connector built-in		
Canon 6030	A1-98-47/47A	Connector built-in		
Canon 6045	A1-98-47/47A	Connector built-in		
Canon 6050	A1-98-47/47A	Connector built-in		
Canon 6055	A1-98-47/47A	Connector built-in		
Canon 6060	A1-98-47/47A	Connector built-in		
Canon 6085	A1-98-47/47A	Connector built-in		
Canon 6150	A1-98-08	Connector built-in		
Canon 6300	A1-98-08	Connector built-in		
Canon 6545	A1-98-47/47A	Connector built-in		
Canon 6560	A1-98-47/47A	Connector built-in		
Canon 6650	A1-98-08	Connector built-in		
Canon 6650II	A1-98-47/47A	Connector built-in		
Canon 6651	A1-98-47/47A	Connector built-in		
Canon 7500	A1-98-08	Connector built-in		
Canon 85	A1-98-08	Connector built-in		
Canon 8530	A1-98-47/47A	Connector built-in		
Canon 90	A1-98-08	Connector built-in		
Canon 9800	A1-98-47/47A	Connector built-in		
Canon IR210	A1-98-47/47A	Connector built-in		
Canon IR2200	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA		
Canon IR8500	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA
Canon NP120	A1-98-08	Connector built-in		
Canon NP200	A1-98-08	Connector built-in		
Canon NP210	A1-98-08	Connector built-in		
Canon NP270	A1-98-08	Connector built-in		
Canon NP300	A1-98-08	Connector built-in		
Canon NP400	A1-98-08	Connector built-in		
Canon NP4050	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon NP500	A1-98-08	Connector built-in		
Canon NP7550	A1-98-08	Connector built-in		
Canon NP80	A1-98-08	Connector built-in		
Canon 105	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA
Canon 2220i	A1-98-47/47A			
Canon 3320	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA
Canon 3320i	A1-98-47/47A		AD7-98-47/47A	
Canon 6020	A1-98-47/47A	Connector built-in	AD7-98-47/47A	

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Canon C400D	A1-98-47/47A		AD7-98-47/47A	
Canon CLC 1140	A1-98-47/47A		AD7-98-47/47A	
Canon CLC 1150	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA
Canon CLC 1180	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA
Canon CLC 3900	A1-98-47/47A		AD7-98-47/47A	
Canon CLC 4000	A1-98-47/47A		AD7-98-47/47A	
Canon CLC 5100	A1-98-47/47A		AD7-98-47/47A	
Canon Color IR 3220	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon ImagePress C1	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR 3045	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA
Canon IR ADVANCE C9075PRO	A1-98-47B	Canon-supplied Copy Control Interface Kit A-1	AD7-98-47B	Canon-supplied Copy Control Interface Kit A-1
Canon IR ADVANCE C5030	A1-98-47B	Canon-supplied Copy Control Interface Kit A-1	AD7-98-47B	Canon-supplied Copy Control Interface Kit A-1
Canon IR ADVANCE C5035	A1-98-47B	Canon-supplied Copy Control Interface Kit A-1	AD7-98-47B	Canon-supplied Copy Control Interface Kit A-1
Canon IR ADVANCE C5045	A1-98-47B	Canon-supplied Copy Control Interface Kit A-1	AD7-98-47B	Canon-supplied Copy Control Interface Kit A-1
Canon IR ADVANCE C5051	A1-98-47B	Canon-supplied Copy Control Interface Kit A-1	AD7-98-47B	Canon-supplied Copy Control Interface Kit A-1
Canon IR ADVANCE C7055	A1-98-47B	Canon-supplied Copy Control Interface Kit A-1	AD7-98-47B	Canon-supplied Copy Control Interface Kit A-1
Canon IR ADVANCE C7065	A1-98-47B	Canon-supplied Copy Control Interface Kit A-1	AD7-98-47B	Canon-supplied Copy Control Interface Kit A-1
Canon IR ADVANCE C9065 PRO 1	A1-98-47B	Canon-supplied Copy Control Interface Kit A-1	AD7-98-47B	Canon-supplied Copy Control Interface Kit A-1
Canon IR2000	A1-98-47/47A		AD7-98-47/47A	
Canon IR2200	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA
Canon IR2270	A1-98-47/47A			
Canon IR2800	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA
Canon IR2870	A1-98-47/47A		AD7-98-47/47A	
Canon IR2880i	A1-98-47/47A		AD7-98-47/47A	
Canon IR3025	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR3035	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR3200	A1-98-47/47A		AD7-98-47/47A	
Canon IR3245	A1-98-47/47A		AD7-98-47/47A	
Canon IR3300	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA
Canon IR3300I	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA
Canon IR3570	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/Copy Audit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Canon IR400	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR4570	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA
Canon IR4570	A1-98-47/47A	Canon Service Model Extrenal Counter Yes	AD7-98-47/47A	
Canon IR5000	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR5020i	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR5050	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR5055	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR5065	A1-98-47	Connector built-in	AD7-98-47/47A	
Canon IR5070	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR5075	A1-98-47/47A		AD7-98-47/47A	
Canon IR550	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR5570	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR5870	A1-98-47A/47A		AD7-98-47/47A	
Canon IR600	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR6000	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR6020	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR6570	A1-98-47/47A		AD7-98-47/47A	
Canon IR7086	A1-98-47/47A		AD7-98-47/47A	
Canon IR7095	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IR7200	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	
Canon IR8500	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA	AD7-98-47/47A	
Canon IR8700	A1-98-47/47A		AD7-98-47/47A	
Canon IR9070	A1-98-47/47A		AD7-98-47/47A	
Canon IR9070	A1-98-47/47A		AD7-98-47/47A	
Canon IRC2880	A1-98-47/47A		AD7-98-47/47A	
Canon IRC3100	A1-98-47/47A		AD7-98-47/47A	
Canon IRC3170x	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IRC3200	A1-98-47/47A		AD7-98-47/47A	
Canon IRC3380	A1-98-47/47A		AD7-98-47/47A	
Canon IRC4080	A1-98-47/47A		AD7-98-47/47A	
Canon IRC4080i	A1-98-47/47A		AD7-98-47/47A	
Canon IRC4580i	A1-98-47/47A		AD7-98-47/47A	
Canon IRC5058	A1-98-47/47A		AD7-98-47/47A	
Canon IRC5180	A1-98-47/47A		AD7-98-47/47A	
Canon IRC5185	A1-98-47A/47A		AD7-98-47/47A	
Canon IRC5800	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IRC6800	A1-98-47/47A	Connector built-in	AD7-98-47/47A	
Canon IRC6870U	A1-98-47/47A		AD7-98-47/47A	
CopyStar CS 620	A1-98-42		AD7-98-42	
CopyStar CS 820	A1-98-42		AD7-98-42	
CopyStar CS-5035	A1-98-42		A1-98-42	
CopyStar CS-5050	A1-98-42		A1-98-42	
CopyStar CS-6030	A1-98-42	Connector built-in		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Gestetner 10502	A1-98-07	Requires Gestetner-supplied harness kit		
Gestetner 2001	A1-98-42	Requires Gestetner-supplied harness kit		
Gestetner 2003	A1-98-42	Requires Gestetner-supplied harness kit		
Gestetner 2020	A1-98-42	Requires Gestetner-supplied harness kit		
Gestetner 2212	A1-98-07	Requires Gestetner-supplied harness kit		
Gestetner 2355	A1-98-42	Requires Gestetner-supplied harness kit		
Gestetner 3245	A1-98-07	Requires Gestetner-supplied harness kit		
Gestetner 3285	A1-98-07			
Gestetner 3370	A1-98-07	Requires Gestetner-supplied harness kit		
Gestetner 3502	A1-98-07	Requires Gestetner-supplied harness kit		
Gestetner 4502P	A1-98-07	Requires Gestetner-supplied harness kit		
Gestetner 6002	A1-98-07	Requires Gestetner-supplied harness kit		
Gestetner 7502	A1-98-07	Depends on what vendor supplies copier - Ricoh (A5095100), Savin (A675401)		
Gestetner DSC332	A1-98-07			
Gestetner DSc445	A1-98-07	Requires Ricoh harness A5095100		
Gestetner DSc460	A1-98-07	Requires Ricoh harness A5095100		
Gestetner DSm415	A1-98-07	Depends on what vendor supplies copier - Ricoh (A5095100), Savin (A675401)		
Gestetner DSm620	A1-98-07	Depends on what vendor supplies copier - Ricoh (A5095100), Savin (A675401)		
Gestetner DSM627	A1-98-07	Requires Ricoh harness A5095100		
Gestetner DSM635	A1-98-07	Requires Ricoh harness A5095100		
Gestetner DSM651	A1-98-07	Depends on what vendor supplies copier - Ricoh (A5095100), Savin (A675401)		
Gestetner DSm660	A1-98-07	Requires Ricoh harness A5095100		
Gestetner DSM675SP	A1-98-07 - if Ricoh c	Depends on what vendor supplies copier - Ricoh (A5095100), Savin (A675401)		
Gestetner DSm735	A1-98-07	Requires Ricoh harness A5095100		
Gestetner DSm755	A1-98-07	Requires Ricoh harness A5095100		
Gestetner DSm790	A1-98-07	Requires Ricoh harness A5095100		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Gestetner PF11	A1-98-42	Requires Gestetner-supplied harness kit		
Hewlett Packard 4345mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard 8050mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard 8060mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard 8100mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard 8150mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard 9000mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard 9040mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard 9050mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard 9055mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard 9065mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard 9500mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard CM8050	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard Color Laser Jet 47	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard M3027mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard M3035MFP	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	
Hewlett Packard M4345mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
Hewlett Packard M5035xs mfp	A1-98-HP MFP	Requires FIH kit from HP	AD7-98-HP MFP	Requires FIH kit from HP
IKON CPP650	A1-98-14A	Harness built into copier	AD7-98-14A	Harness built into copier
IKON PrintCentrePro 1050	A1-98-14A	Harness built into copier	AD7-98-14A	Harness built into copier
Imagistics 252of	A1-98-14A	Harness built into copier	AD7-98-14A	Harness built into copier
Imagistics CM2020 (CM20)	custom			
Imagistics IM6020				
Imagistics IM6530	A1-98-07	Harness built into copier		
Imagistics ZD65	A1-98-07	Harness built into copier		
Kodak 200	A1-98-03	Requires Kodak-supplied harness kit		
Kodak 2085	A1-98-03	Requires Kodak-supplied harness kit		
Kodak 2110	A1-98-08	Requires Kodak-supplied harness kit		
Kodak 2120	A1-98-08	Requires Kodak-supplied harness kit		
Kodak 225	A1-98-03	Requires Kodak-supplied harness kit		
Kodak 235	A1-98-03	Requires Kodak-supplied harness kit		
Kodak 250	A1-98-03	Requires Kodak-supplied harness kit		
Kodak 300	A1-98-03	Requires Kodak-supplied harness kit		
Kodak 85	A1-98-08	Requires Kodak-supplied harness kit		
Kodak 90	A1-98-08	Requires Kodak-supplied harness kit		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Kodak 95	A1-98-47/47A	Requires Kodak-supplied harness kit		
Kodak IM40	A1-98-08	Requires Kodak-supplied harness kit		
Kodak IS70	A1-98-08	Requires Kodak-supplied harness kit		
Konica 2028	A1-98-10	Harness built into copier		
Konica 2125	A1-98-10	Harness built into copier		
Konica 2590	A1-98-10	Harness built into copier		
Konica 3135	A1-98-10	Harness built into copier		
Konica 3235	A1-98-10	Harness built into copier		
Konica 3290	A1-98-10	Harness built into copier		
Konica 4045	A1-98-10	Harness built into copier		
Konica 4090	A1-98-10	Harness built into copier		
Konica 4145	A1-98-10	Harness built into copier		
Konica 4155	A1-98-10	Harness built into copier		
Konica 4290	A1-98-10	Harness built into copier		
Konica 4291	A1-98-10	Harness built into copier		
Konica 4345	A1-98-10	Harness built into copier		
Konica 5503	A1-98-10	Harness built into copier		
Konica 6090	A1-98-10	Harness built into copier		
Konica 6190	A1-98-10	Harness built into copier		
Konica 7020	A1-98-10	Harness built into copier		
Konica 7022	A1-98-14/14A	Harness built into copier		
Konica 7030	A1-98-10	Harness built into copier		
Konica 7033	A1-98-10	Harness built into copier		
Konica 7040	A1-98-10	Harness built into copier		
Konica 7044	A1-98-10	Harness built into copier		
Konica 7045	A1-98-10	Harness built into copier		
Konica 7050	A1-98-10	Harness built into copier		
Konica 7055	A1-98-10	Harness built into copier		
Konica 7060	A1-98-10	Harness built into copier		
Konica 7065	A1-98-14/14A	Harness built into copier		
Konica 7075	A1-98-14/14A OR A	Harness built into copier		
Konica 7085	A4-98-14/14A			
Konica 7090	A4-98-14/14A	Harness built into copier		
Konica 7130	A4-98-14/14A	Harness built into copier		
Konica 7145	A1-98-14/14A	Harness built into copier		
Konica 7150	A1-98-10	Harness built into copier		
Konica 7155	A1-98-14/14A	Harness built into copier		
Konica 7165	A1-98-14/14A	Harness built into copier		
Konica 7228	A1-98-14A	Harness built into copier		
Konica 7255	A1-98-14/14A	Harness built into copier		
Konica 7272	A1-98-14/14A			
Konica 7490	A1-98-10	Harness built into copier		
Konica DL750	A1-98-10	Harness built into copier		
Konica Minolta 362	A1-98-14A	Harness built into copier		
Konica Minolta 421	A1-98-14A	Harness built into copier		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Konica Minolta 501	A1-98-14A	Harness built into copier		
Konica Minolta 7222 Bizhub	A1-98-14/14A or A1-98-14Z			
Konica Minolta 8031	A1-98-14Z	Harness built into copier		
Konica Minolta Bizhub 200	A1-98-14Z/A1-98-14	Harness built into copier		
Konica Minolta Bizhub 250C	A1-98-14Z			
Konica Minolta Bizhub 350	A1-98-14A	Harness built into copier		
Konica Minolta Bizhub 361	A1-98-14A	Harness built into copier		
Konica Minolta Bizhub 420	A1-98-14A			
Konica Minolta Bizhub 450	A1-98-14Z	Harness built into copier		
Konica Minolta Bizhub 501	A1-98-14A	Harness built into copier		
Konica Minolta Bizhub 600	A1-98-10* or A1-98-	*Requires KM keycounter harness 1206K0010		
Konica Minolta Bizhub 601	A1-98-14A	Harness built into copier		
Konica Minolta Bizhub 7235	A1-98-14A			
Konica Minolta Bizhub 750	A1-98-14A	Harness built into copier		
Konica Minolta Bizhub 751	A1-98-14A	Harness built into copier		
Konica Minolta Bizhub C203	A1-98-14A			
Konica Minolta BizHub C350	A1-98-14A	Harness built into copier		
Konica Minolta BizHub C353	A1-98-14A	Harness built into copier		
Konica Minolta BizHub C451	A1-98-14A	Harness built into copier		
Konica Minolta Bizhub C452	A1-98-14A			
Konica Minolta Bizhub 360	A1-98-14A			
Konica Minolta Bizhub C550	A1-98-14A	Harness built into copier		
Konica Minolta Bizhub C652	A1-98-14A	Harness built into copier		
Konica Minolta Bizhub Pro 1050	A1-98-14A	Harness built into copier	AD7-98-14A	Harness built into copier
Konica Minolta Bizhub Pro 920	A1-98-14A	Harness built into copier	AD7-98-14A	Harness built into copier
Konica Minolta Bizhub Pro 950	A1-98-14A	Harness built into copier	AD7-98-14A	Harness built into copier
Konica Minolta Bizhub Pro C6500	A1-98-14A	Harness built into copier	AD7-98-14A	Harness built into copier
Konica Minolta C351	A1-98-14Z, rarely A1-98-14A		AD7-98-14Z	
Konica Minolta C352	A1-98-14Z			
Konica Minolta C450	A1-98-14Z			
Konica Minolta C500	A1-98-14A	Harness built into copier		
Konica Minolta C550	A1-98-14A			
Konica Minolta DI2010F	A1-98-14/14A			
Konica Minolta DI2510	A1-98-14/14A	Harness built into copier		
Konica Minolta DI3010	A1-98-14A	Harness built into copier		
Konica Minolta DI3510f	A1-98-14A	Harness built into copier		
Konica Minolta DI450	A1-98-14Z			
Konica Minolta DI470	A1-98-14A	Harness built into copier		
Konica Minolta DI5510	A1-98-14A	Harness built into copier		
Konica Minolta DI7210	A1-98-14A	Harness built into copier		
Konica Minolta 7228 Bizhub	A1-98-14A			
Konica Minolta 7255 Bizhub	A1-98-14A			
Konica Minolta 7272 Bizhub	A1-98-14A			
Kyocera KM-3060	A1-98-42			
Kyocera Mita 3050	A1-98-42		AD7-98-42	N/A
Kyocera Mita 8530	A1-98-10	Harness built into copier	AD7-98-10	N/A

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Kyocera TASKalfa 300ci	A1-98-42	Requires Kyocera-supplied harness kit	AD7-98-42	
Kyocera TASKalfa 400ci	A1-98-42	Requires Kyocera-supplied harness kit	AD7-98-42	
Kyocera TASKalfa 620	A1-98-42	Requires Kyocera-supplied harness kit	AD7-98-42	
Kyocera TASKalfa 820	A1-98-42	Requires Kyocera-supplied harness kit	AD7-98-42	
Kyocera/Mita 2030	A1-98-42		AD7-98-42	N/A
Kyocera/Mita 2530	A1-98-42	Harness built into copier	AD7-98-42	N/A
Kyocera/Mita 3035	A1-98-42		AD7-98-42	N/A
Kyocera/Mita 3530	A1-98-42		AD7-98-42	N/A
Kyocera/Mita 4035	A1-98-42	Harness built into copier	AD7-98-42	N/A
Kyocera/Mita 4035E	A1-98-42			
Kyocera/Mita 4050i	A1-98-42	Harness built into copier	AD7-98-42	N/A
Kyocera/Mita 4530	A1-98-42	Harness built into copier	AD7-98-42	N/A
Kyocera/Mita 5035	A1-98-42	Harness built into copier	AD7-98-42	N/A
Kyocera/Mita 5530	A1-98-42	Harness built into copier	AD7-98-42	N/A
Kyocera/Mita 6230	A1-98-42	Harness built into copier	AD7-98-42	N/A
Kyocera/Mita 6330	A1-98-42	Harness built into copier	AD7-98-42	N/A
Kyocera/Mita 7360	A1-98-10	Harness built into copier	AD7-98-42	N/A
Kyocera/Mita 7530	A1-98-42	Harness built into copier	AD7-98-42	N/A
Kyocera/Mita 8030	A1-98-42	Harness built into copier	AD7-98-42	N/A
Kyocera/Mita C2230	A1-98-10	Requires "keycounter kit" from Kyocera Mita	AD7-98-10	N/A
Kyocera/Mita C3130	A1-98-14Z	Harness built into copier	AD71-98-14Z	N/A
Kyocera/Mita KM-2050	A1-98-42	requires Kyocera-supplied Keycounter Harness 2C960110	AD7-98-42	N/A
Kyocera/Mita KM-2550	A1-98-42	requires Kyocera-supplied Keycounter Harness 2C960110	AD71-98-42	N/A
Kyocera/Mita KM-5050	A1-98-42	Harness built into copier	AD71-98-42	N/A
Kyocera/Mita KM-6030	A1-98-42	Harness built into copier	AD71-98-42	N/A
Lanier 3616	A1-98-47/47A			
Lanier 483	A1-98-13			
Lanier 5020	A1-98-13			
Lanier 5265	A1-98-13			
Lanier 5365	A1-98-13			
Lanier 5455	A1-98-07			
Lanier 5470	A1-98-07			
Lanier 5622	A1-98-07			
Lanier 5635	A1-98-07			
Lanier 5645	A1-98-07			
Lanier 5722	A1-98-13			
Lanier 6020	A1-98-13			
Lanier 6242	A1-98-13			
Lanier 6255	A1-98-13			
Lanier 6260	A1-98-13			
Lanier 6360	A1-98-13			

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Lanier 6360	A1-98-13			
Lanier 6483	A1-98-47/47A			
Lanier 6523	A1-98-13			
Lanier 6550	A1-98-13			
Lanier 6583	A1-98-47/47A			
Lanier 6765	A1-98-13			
Lanier 6775	A1-98-13			
Lanier 7165	A1-98-14/14A			
Lanier 7365	A1-98-13			
Lanier 7375	A1-98-13			
Lanier LD0120d	A1-98-07	Requires Lanier-supplied harness GA5095100		
Lanier LD015	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD016	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD116	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD118d	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD120D	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD127	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD135	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD145	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD175	A1-98-13	Requires Lanier-supplied Harness		
Lanier LD245	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD275	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD335C	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD345C	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD425c	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Lanier LD430C	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD435C	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LD60C	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LDD 245	A1-98-07	Requires Ricoh-supplied harness kit A5095100		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Lanier LDO105	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LDO60	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LDO60	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LDO75	A1-98-13	Requires Lanier-supplied Harness		
Lanier LDO90	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Lanier LW310	no support			
Minolta 2010	A1-98-14/14A	Harness built into copier		
Minolta 2030	A1-98-14/14A	Harness built into copier		
Minolta 2050	A1-98-14/14A	Harness built into copier		
Minolta 3055	A1-98-14/14A	Harness built into copier		
Minolta 4050	A1-98-14/14A	Harness built into copier		
Minolta 4230	A1-98-14/14A	Harness built into copier		
Minolta 4233	A1-98-14/14A	Harness built into copier		
Minolta 5050	A1-98-14/14A	Harness built into copier		
Minolta 5520	A1-98-14/14A	Harness built into copier		
Minolta 6000	A1-98-14/14A	Harness built into copier		
Minolta 8016	A1-98-14/14A	Harness built into copier		
Minolta 8603	A1-98-14/14A	Harness built into copier		
Minolta 9760	A1-98-14/14A	Harness built into copier		
Minolta 3050	A1-98-14/14A	Harness built into copier		
Minolta 350	A1-98-14/14A	Harness built into copier		
Minolta 4230	A1-98-14/14A	Harness built into copier		
Minolta 4233	A1-98-14	Harness built into copier		
Minolta 4300	A1-98-14	Harness built into copier		
Minolta 4301	A1-98-14	Harness built into copier		
Minolta 450	A1-98-14	Harness built into copier		
Minolta 470	A1-98-14	Harness built into copier		
Minolta 5050	A1-98-14	Harness built into copier		
Minolta 510	A1-98-14	Harness built into copier		
Minolta 520	A1-98-14	Harness built into copier		
Minolta 530	A1-98-14	Harness built into copier		
Minolta 5320	A1-98-14	Harness built into copier		
Minolta 5400	A1-98-14/14A	Harness built into copier		
Minolta 5420	A1-98-14/14A	Harness built into copier		
Minolta 5520	A1-98-14	Harness built into copier		
Minolta 570	A1-98-14/14A	Harness built into copier		
Minolta 6000	A1-98-14	Harness built into copier		
Minolta 650	A1-98-14	Harness built into copier		
Minolta 710	A1-98-14	Harness built into copier		
Minolta 8010	A1-98-14	Harness built into copier		
Minolta 8015	A1-98-14	Harness built into copier		
Minolta 850	A1-98-14	Harness built into copier		
Minolta 9760	A1-98-14	Harness built into copier		
Minolta CF2002	A1-98-14Z			

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Minolta CF3102	A1-98-14Z			
Minolta DI1610	A1-98-14/14A	Harness built into copier		
Minolta DI1811	A1-98-14/14A	Harness built into copier		
Minolta DI200	A1-98-14/14A	Harness built into copier		
Minolta DI200F	A1-98-14/14A	Harness built into copier		
Minolta DI250	A1-98-14/14A	Harness built into copier		
Minolta DI251	A1-98-14/14A	Harness built into copier		
Minolta DI3510	A1-98-14/14A	Harness built into copier		
Minolta DI351F	A1-98-14/14A	Harness built into copier		
Minolta DI450	A1-98-14/14A	Harness built into copier		
Minolta DI470	A1-98-14/14A	Harness built into copier		
Minolta DI550	A1-98-14/14A	Harness built into copier		
Minolta DI551	A1-98-14/14A	Harness built into copier		
Minolta DI5510	A1-98-14A	Harness built into copier		
Minolta DI552	A1-98-14/14A	Harness built into copier		
Minolta DI620	A1-98-14, 14A	Harness built into copier		
Minolta DI650	A1-98-14, 14A	Harness built into copier		
Minolta DI750	A1-98-10	Harness built into copier		
Minolta EP450	A1-98-14	Harness built into copier		
Minolta EP5000	A1-98-14/14A	Harness built into copier		
Minolta EP6000	A1-98-14/14A	Harness built into copier		
Mita 162	A1-98-26	Harness built into copier		
Mita 1855	A1-98-42	Harness built into copier		
Mita 2254	A1-98-42	Harness built into copier		
Mita 2465	A1-98-42	Harness built into copier		
Mita 3055	A1-98-42	Harness built into copier		
Mita 3132	A1-98-42	Harness built into copier		
Mita 3648	Custom			
Mita 3785	A1-98-42	Harness built into copier		
Mita 4090	A1-98-42	Harness built into copier		
Mita 4530	A1-98-42	Harness built into copier		
Mita 4585	A1-98-42	Harness built into copier		
Mita 4685	A1-98-42	Harness built into copier		
Mita 5230	A1-98-42	Harness built into copier		
Mita 5555	A1-98-42	Harness built into copier		
Mita 5585	A1-98-10	Harness built into copier		
Mita 5590	A1-98-42	Harness built into copier		
Mita 5690	A1-98-42	Harness built into copier		
Mita 6090	A1-98-42	Harness built into copier		
Mita 6230	A1-98-42	Harness built into copier		
Mita 6500	A1-98-42	Harness built into copier		
Mita 6590	A1-98-42	Harness built into copier		
Mita 6595	A1-98-42	Harness built into copier		
Mita 7085	A1-98-42	Harness built into copier		
Mita 7090	A1-98-42	Harness built into copier		
Mita 8090	A1-98-42	Harness built into copier		
Mita 8585	A1-98-42	Harness built into copier		
Mita 9285	A1-98-42	Harness built into copier		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Mita DC232	A1-98-42	Harness built into copier		
Mita DC4090	A1-98-42	Harness built into copier		
Mita DC6500	A1-98-42	Harness built into copier		
Monroe (Mita313)	A1-98-42	Harness built into copier		
Monroe (Mita5585)	A1-98-42	Harness built into copier		
Monroe 1260+A89	A1-98-42	Harness built into copier		
NEC IT 45C4	A1-98-14A	Harness built into copier		
Oce 1825	Custom			
Oce 1900	Custom			
Oce 2475	A1-98-51			
Oce 3045	A1-98-51			
Oce 3155/3165	A1-98-51	Requires OCE-supplied CCD interface		
OCE 4010	A1-98-53-2A	Requires Sharp-supplied DVEND harness		
Oce CM2520	???			
Oce CS650 Pro	A1-98-14A	Harness built into copier	AD7-98-14A	Harness built into copier
Oce CS665	A1-98-14A	Harness built into copier	AD7-98-14A	
Oce Imagistics cm3120	A1-98-14Z			
Oce Imagistics CM4520	A1-98-07B	requires OCE-supplied key counter harness (parts 4004-6870-01 and 1134-6827-01)		
Oce Imagistics CM4520	A1-98-14A	Harness built into copier		
Oce Imagistics CM4521				
Oce Imagistics CM4530	Unique harness	Unique harness		
Oce Imagistics IM5520	A1-98-14A	Harness built into copier		
Oce Imagistics IM5530	A1-98-07A	Harness built into copier		
Oce Imagistics IM5530	A1-98-14A	Harness built into copier		
Oce Imagistics IM8130	A1-98-07 unique	Unique harness		
OCE OP33	A1-98-47/47A	Requires Canon-supplied harness kit PN 7096A002AA		
Oce VarioPrint 2060		Requires CCD Interface for external copier control device		
Oce VarioPrint 2062		Requires CCD Interface for external copier control device		
Oce VarioPrint 2070		Requires CCD Interface for external copier control device		
Oce VarioPrint 2075		Requires CCD Interface for external copier control device		
Oce VarioPrint 2090		Requires CCD Interface for external copier control device		
Oce VarioPrint 2110		Requires CCD Interface for external copier control device		
OCECS620	A1-98-14A	Harness built into copier	AD7-98-14A	Harness built into copier
P/Bowes 640	A1-98-07			
P/Bowes 750	A1-98-07			
P/Bowes 9045	A1-98-42			

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/Copy Audit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
P/Bowes 9070	A1-98-42			
P/Bowes 9326	A1-98-07			
P/Bowes 9332	A1-98-25,25A			
P/Bowes C160	A1-98-07			
P/Bowes C180	A1-98-07			
P/Bowes DI650	A1-98-07			
P/Bowes DL460	A1-98-07			
P/Bowes DL520	A1-98-07			
P/Bowes DL550	A1-98-07			
P/Bowes 4500	A1-98-31			
P/Bowes C235	A1-98-07			
P/Bowes C350	A1-98-14/14A	requires keyblock change		
P/Bowes C450	A1-98-14/14A			
P/Bowes C600	A1-98-14/14A			
P/Bowes C62	A1-98-07			
P/Bowes C620	A1-98-07			
P/Bowes C650	A1-98-07			
P/Bowes M562	A1-98-07			
Panasonic 1520	A1-98-25			
Panasonic 1780	A1-98-25			
Panasonic 1800	A1-98-25			
Panasonic 1801	A1-98-25			
Panasonic 3000	A1-98-25			
Panasonic 3001	A1-98-25			
Panasonic 3010	A1-98-25/25A	Requires Panasonic-supplied harness kit		
Panasonic 3270	A1-98-25/25A	Requires Panasonic-supplied harness kit		
Panasonic 3280	A1-98-25	Requires Panasonic-supplied harness kit		
Panasonic 4520	A1-98-25	Requires Panasonic-supplied harness kit		
Panasonic 4630	A1-98-25	Requires Panasonic-supplied harness kit		
Panasonic 6070	A1-98-25	Requires Panasonic-supplied harness kit		
Panasonic 7160	A1-98-25	Requires Panasonic-supplied harness kit		
Panasonic 7728	A1-98-25	Requires Panasonic-supplied harness kit		
Panasonic 7750	A1-98-14/14A	Requires Panasonic-supplied harness kit		
Panasonic 7781	A1-98-25	Requires Panasonic-supplied harness kit		
Panasonic DP-1520P	A1-98-25F	Requires Panasonic-supplied harness kit - DA-KH180		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Panasonic DP1810	A1-98-25	Requires Panasonic-supplied harness kit		
Panasonic DP2000	A1-98-25	Requires Panasonic-supplied harness kit		
Panasonic DP2010	A1-98-25	Requires Panasonic-supplied harness kit		
Panasonic DP2500	A1-98-25	Requires Panasonic-supplied harness kit "DA-KH200"		
Panasonic DP3300	A1-98-25	Requires Panasonic-supplied harness kit		
Panasonic DP3500	A1-98-25	Requires Panasonic-supplied harness kit		
Panasonic DP3510	A1-98-25F	Requires Panasonic-supplied harness kit - DZTY000128		
Panasonic DP4510	A1-98-25F	Requires Panasonic-supplied harness kit - DZTY000128		
Panasonic DP6010	A1-98-25F	Requires Panasonic-supplied harness kit		
Panasonic DP-8016P	A1-98-25F	Requires Panasonic-supplied harness kit - DA-KH180		
Panasonic DP-8020E	A1-98-25F	Requires Panasonic-supplied harness kit - DA-KH180		
Panasonic DP-8020P	A1-98-25F	Requires Panasonic-supplied harness kit - DA-KH180		
Panasonic Workio 6020	A1-98-25F	Requires Panasonic-supplied harness kit - DZTY000128		
Ricoh 3006	A1-98-07	Harness built into copier		
Ricoh 3213	see notes in Ricoh file			
Ricoh 4006	A1-98-07	Harness built into copier		
Ricoh 4010	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 4060	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 4106	A1-98-07	Harness built into copier		
Ricoh 4480	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 4700	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 4727	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 5070	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 5540	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 5560	A1-98-07	Requires Ricoh-supplied harness kit		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Ricoh 5570	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 5590	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 5733	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 5780	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 6080	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 6085	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 6200	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 6600	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 6645	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 6655	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 6665	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh 6750	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 7060	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 7650	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh 7660	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 7870	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh 2090	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh 3025	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh 3030SP	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh 3260C	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh 7650	A1-98-07	Requires Ricoh-supplied harness kit		
Ricoh Aficio 1022	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 1027	A1-98-07	Requires Ricoh-supplied harness kit A5095100		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Ricoh Aficio 1045	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 1060	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 1075	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Aficio 1085	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 1105	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 1224	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 1232	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 1515	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 1600	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2000	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2016	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2018	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2020	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2027	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2035	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2035 ESP	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2045 S/F	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2051	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2060	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2075	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2090	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2105	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2232	A1-98-07	Requires Ricoh-supplied harness kit A5095100		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Ricoh Aficio 2238	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 240W	no support			
Ricoh Aficio 250	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 2550	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 3025	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 3025	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 3030	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 3035	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 3045	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 3235C	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 3260C	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 3350	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 450	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 551	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 5560	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 650	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 700	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio 850	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio MP 161	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Aficio MP 2510	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio MP 6001	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20 or AD7	Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Aficio MP C2500	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Aficio MP C3000	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Aficio MP C3300	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Ricoh Aficio MP C3500	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Aficio MP C4500	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Aficio MP C5000	A1-98-07	Requires Ricoh-supplied harness kit A5095100		Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Aficio MP C7500	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Aficio MP W3600			AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Aficio MP1100	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio MP1350	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio MP171	A1-98-07-20	Optional Counter Interface Unit Type	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Aficio MP5500	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio MP5560	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio MP6000	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio MP6500	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio MP C6501SP	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio MP7000	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio MP7500	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Aficio MP8000	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Aficio MP9000	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Aficio MPC5000	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Ricoh Priport DX 4542	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Priport DX3340	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Priport DX4640PD	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Ricoh Pro 1107EX	A1-98-07	Requires Ricoh-supplied harness kit A5095100	b&w	
Ricoh Pro 1357EX	A1-98-07	Requires Ricoh-supplied harness kit A5095100	b&w	
Ricoh Pro 906EX	A1-98-07	Requires Ricoh-supplied harness kit A5095100	b&w	

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Ricoh Pro 907EX	A1-98-07	Requires Ricoh-supplied harness kit A5095100	b&w	
Ricoh Pro C900	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Royal 2070	A1-98-42			
Royal 2070	A1-98-42			
Royal 2140	A1-98-42			
Royal 2140	A1-98-42			
Royal 2235	A1-98-42			
Royal 2235	A1-98-42			
Royal 2240	A1-98-42			
Royal 2240	A1-98-42			
Royal 4003	A1-98-10			
Royal 4003	A1-98-10			
Royal 5003	A1-98-10			
Royal 5003	A1-98-10			
Royal 5503	A1-98-10			
Royal 5503	A1-98-10			
Royal 6230	A1-98-42			
Royal 6230	A1-98-42			
Royfax 115	A1-98-10			
Royfax 115	A1-98-10			
Royfax 122	A1-98-10			
Royfax 122	A1-98-10			
Royfax 130	A1-98-10			
Royfax 130	A1-98-10			
Royfax 145R	A1-98-10			
Royfax 145R	A1-98-10			
Savin 2055DP	A1-98-07	Requires Savin-supplied harness kit		
Savin 2060	A1-98-07	Requires Savin-supplied harness kit		
Savin 2070	A1-98-07	Requires Savin-supplied harness kit		
Savin 2085	A1-98-07	Requires Savin-supplied harness kit		
Savin 2527	A1-98-07	Requires Savin-supplied harness kit (A674-5401)		
Savin 2535P	A1-98-07	Requires Savin-supplied harness kit (A674-5401)		
Savin 2545P	A1-98-07	Requires Savin-supplied harness kit (A674-5401)		
Savin 2560	A1-98-07	Requires Savin-supplied harness kit (A674-5401)		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Savin 2575	A1-98-07	Requires Savin-supplied harness kit (A674-5401)		
Savin 306	A1-98-07	Harness built into copier		
Savin 326 Color	A1-98-07	Harness built into copier		
Savin 3515	A1-98-07	Requires Savin-supplied harness kit (A674-5401)		
Savin 4035	A1-98-07	Requires Savin-supplied harness kit (A674-5401)		
Savin 4045	A1-98-07	Requires Savin-supplied harness kit (A674-5401)		
Savin 4051SP	A1-98-07	Requires Savin-supplied harness kit (A674-5401)		
Savin 4075	A1-98-07	Requires Savin-supplied harness kit (A674-5401)		
Savin 410 Color	A1-98-07	Harness built into copier		
Savin 413	A1-98-07	Harness built into copier		
Savin 600	A1-98-07			
Savin 7035	A1-98-07			
Savin 7040	A1-98-07			
Savin 7045	A1-98-07			
Savin 7065	A1-98-07			
Savin 7350	A1-98-07			
Savin 755	A1-98-07			
Savin 760	A1-98-07			
Savin 7640	A1-98-07			
Savin 765	A1-98-07			
Savin 770	A1-98-07			
Savin 775	A1-98-07			
Savin 780	A1-98-07			
Savin 790	A1-98-07			
Savin 800	A1-98-07			
Savin 8020	A1-98-07			
Savin 8035	A1-98-07	Requires Savin-supplied harness kit		
Savin 8055	A1-98-07	Requires Savin-supplied harness kit		
Savin 840	A1-98-07			
Savin 8600	A1-98-07			
Savin 870	A1-98-07			
Savin 880	A1-98-07			
Savin 895	A1-98-07			
Savin 9032	A1-98-07	Requires Savin-supplied harness kit		
Savin 9060	A1-98-07	Requires Ricoh Harness A5095100		
Savin 9450	A1-98-07	Requires Savin-supplied harness kit		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Savin 9550	A1-98-07	Requires Savin-supplied harness kit		
Savin 9940	A1-98-07	Requires Savin-supplied harness kit		
Savin 9944	A1-98-07	Requires Savin-supplied harness kit		
Savin 9945	A1-98-07	Requires Savin-supplied harness kit		
Savin 9955	A1-98-07	Requires Savin-supplied harness kit		
Savin 9965	A1-98-07	Requires Savin-supplied harness kit		
Savin C2525	A1-98-07	Requires Savin-supplied harness kit		
Savin C3333	A1-98-07	Requires Ricoh Harness A5095100		
Savin C2838	A1-98-07	Requires Ricoh Harness A5095100	AD7-98-07-20	Optional Counter Interface Unit Type A. Product ID 41301
Selex 2320	A1-98-08	Harness built into copier		
Selex 3020	A1-98-47/47A	Harness built into copier		
Selex 7280	A1-98-47	Harness built into copier		
Sharp 2022	A1-98-18	Harness built into copier		
Sharp 2035	A1-98-18	Harness built into copier		
Sharp 2060	A1-98-18	Harness built into copier		
Sharp 2075	plug straight into ks			
Sharp 2175	Sharp 2075			
Sharp 3062	Sharp 2075			
Sharp 3075	plug straight into ks			
Sharp 5216AG	A1-98-53-2	DVENDPG		
Sharp 5220AG	A1-98-53-2	DVENDPG		
Sharp 7320	A1-98-18	Harness built into copier		
Sharp 7900	A1-98-18	Harness built into copier		
Sharp 9510	A1-98-18	Harness built into copier		
Sharp 9750	A1-98-18	Harness built into copier		
Sharp 9800	A1-98-18	Harness built into copier		
Sharp 9950	A1-98-18	Harness built into copier		
Sharp AL-1600	A1-98-53-2	DVENDPG		
Sharp AL-1610	A1-98-53-2	DVENDPG		
Sharp AR-160	A1-98-53-2	DVENDPG		
Sharp AR-160j	A1-98-53-2	DVENDPG		
Sharp AR-161	A1-98-53-2	DVENDPG		
Sharp AR-161 Europe	A1-98-53-2A	INVENDKIT2		
Sharp AR-162	A1-98-53-2A	DVENDPG		
Sharp AR-162J	A1-98-53-2	DVENDPG		
Sharp AR-163	A1-98-53-2	DVENDPG		
Sharp AR-163 Europe	A1-98-53-2A	INVENDKIT2		
Sharp AR-163J	A1-98-53-2	DVENDPG		
Sharp AR-168	no interface available			
Sharp AR-200	A1-98-53-2	DVENDPG		
Sharp AR-200 Europe	A1-98-53-2A	INVENDKIT2		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Sharp AR-200J	A1-98-53-2	DVENDPG		
Sharp AR-200S	A1-98-53-2	DVENDPG		
Sharp AR-200SJ	A1-98-53-2	DVENDPG		
Sharp AR-201	A1-98-53-2	DVENDPG		
Sharp AR-201J	A1-98-53-2	DVENDPG		
Sharp AR-201S	A1-98-53-2	DVENDPG		
Sharp AR-201SJ	A1-98-53-2	DVENDPG		
Sharp AR-205	A1-98-53-2	DVENDPG		
Sharp AR-205 Europe	A1-98-53-2A	INVENDKIT2		
Sharp AR-205J	A1-98-53-2	DVENDPG		
Sharp AR-206 Europe	A1-98-53-2A	INVENDKIT2		
Sharp AR-207	A1-98-53-2	DVENDPG		
Sharp AR-207J	A1-98-53-2	DVENDPG		
Sharp AR-235	A1-98-53-2	DVENDAG		
Sharp AR-235 Europe	A1-98-53-2A	INVENDKIT2		
Sharp AR-237	A1-98-53-2	DVENDLG		
Sharp AR-250	A1-98-53-2	DVENDCG		
Sharp AR-250J	A1-98-53-2	DVENDCG		
Sharp AR-275	A1-98-53-2	DVENDAG		
Sharp AR-275 Europe	A1-98-53-2A	INVENDKIT2		
Sharp AR-280	A1-98-53-2	DVENDCG		
Sharp AR-281	A1-98-53-2	DVENDCG		
Sharp AR-281J	A1-98-53-2	DVENDCG		
Sharp AR-285	A1-98-53-2	DVENDCG		
Sharp AR-286	A1-98-53-2	DVENDCG		
Sharp AR-286J	A1-98-53-2	DVENDCG		
Sharp AR-287	A1-98-53-2	DVENDCG		
Sharp AR287 Europe	A1-98-53-2A	INVENDKIT1		
Sharp AR-287J	A1-98-53-2	DVENDCG		
Sharp AR-335	A1-98-53-2	DVENDCG		
Sharp AR-336	A1-98-53-2	DVENDCG		
Sharp AR-336J	A1-98-53-2	DVENDCG		
Sharp AR-337	A1-98-53-2	DVENDCG		
Sharp AR-337 Europe	A1-98-53-2A	INVENDKIT1		
Sharp AR-337J	A1-98-53-2	DVENDCG		
Sharp AR-350	A1-98-53-2	DVENDTG		
Sharp AR-405	A1-98-53-2	DVENDCG		
Sharp AR-405J	A1-98-53-2	DVENDCG		
Sharp AR-407	A1-98-53-2	DVENDCG		
Sharp AR-407	A1-98-53-2A	INVENDKIT1		
Sharp AR-407J	A1-98-53-2	DVENDCG		
Sharp AR-450	A1-98-53-2	DVENDTG		
Sharp AR-450	A1-98-53-2	DVENDTG		
Sharp AR-501	A1-98-53-2	DVENDCG		
Sharp AR-501J	A1-98-53-2	DVENDCG		
Sharp AR-505	A1-98-53-2	DVENDCG		
Sharp AR-505J	A1-98-53-2	DVENDCG		
Sharp AR-507	A1-98-53-2	DVENDCG		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopyAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Sharp AR-507 Europe	A1-98-53-2A	INVENDKIT1		
Sharp AR-507J	A1-98-53-2	DVENDCCG		
Sharp AR-5316	A1-98-53-2A	DVENDPEG		
Sharp AR-650	A1-98-53-2	DVENDHG		
Sharp AR-651	A1-98-53-2	DVENDHG		
Sharp AR-800	A1-98-53-2	DVENDHG		
Sharp AR-810	A1-98-53-2	DVENDHG		
Sharp AR-BC260	A1-98-53-2A	DVENDWG		
Sharp AR-BC320	A1-98-53-2A	DVENDWG		
Sharp AR-C150	A1-98-53-2	DVENDBG		
Sharp AR-C150 Europe	A1-98-53-2A	INVENDKIT4		
Sharp AR-C160	A1-98-53-2	DVENDBG		
Sharp AR-C160 Europe	A1-98-53-2A	INVENDKIT4		
Sharp AR-C250	A1-98-53-2	DVENDBG		
Sharp AR-C250 Europe	A1-98-53-2A	INVENDKIT4		
Sharp AR-C250 Europe	A1-98-53-2A	INVENDKIT4		
Sharp AR-C260M	A1-98-53-2	DVENDWG		
Sharp AR-C260P	A1-98-53-2	DVENDWG		
Sharp AR-C270	A1-98-53-2	DVENDBG		
Sharp AR-C330	A1-98-53-2A	DVENDBG		
Sharp AR-DM2005	A1-98-53-2	DVENDPG		
Sharp AR-DM2010	A1-98-53-2	DVENDPG		
Sharp AR-DM2015	A1-98-53-2	DVENDPG		
Sharp AR-M 350N	A1-98-53-2	DVENDTG		
Sharp AR-M160	A1-98-53-2	DVENDPEG		
Sharp AR-M160 Europe	A1-98-53-2A	INVENDKIT3		
Sharp AR-M162	A1-98-53-2	DVENDPEG		
Sharp AR-M205	A1-98-53-2	DVENDPEG		
Sharp AR-M205 Europe	A1-98-53-2A	INVENDKIT3		
Sharp AR-M207	A1-98-53-2A	DVENDPEG		
Sharp AR-M208	A1-98-53-2	DVENDaG		
Sharp AR-M235	A1-98-53-2	DVENDLG		
Sharp AR-M235	A1-98-53-2	DVENDAG		
Sharp AR-M236 Europe	A1-98-53-2A	INVENDKIT3		
Sharp AR-M237	A1-98-53-2A	DVENDAG		
Sharp AR-M257	A1-98-53-2A	DVENDAG		
Sharp AR-M275	A1-98-53-2	DVENDLG		
Sharp AR-M276	A1-98-53-2A	INVENDKIT3		
Sharp AR-M277	A1-98-53-2A	DVENDAG		
Sharp AR-M280	A1-98-53-2	DVENDTG		
Sharp AR-M317	A1-98-53-2A	DVENDAG		
Sharp AR-M335N	A1-98-53-2	DVENDTG		
Sharp AR-M350	A1-98-53-2A	DVENDTG		
Sharp AR-M351N	A1-98-53-2A	AR-ASDSVEND2/INVENDKIT3		
Sharp AR-M355	A1-98-53-2A	DVENDTG		
Sharp AR-M450	A1-98-53-2A	DVENDTG		
Sharp AR-M450 Europe	A1-98-53-2A	INVENDKIT3		
Sharp AR-M451N	A1-98-53-2A	AR-ASDSVEND2/INVENDKIT3		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopyAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Sharp AR-M455	A1-98-53-2A	DVENDTG		
Sharp AR-M550	A1-98-53-2	DVENDDDG		
Sharp AR-M550 Europe	A1-98-53-2A	INVENDKIT3		
Sharp AR-M620	A1-98-53-2	DVENDDDG		
Sharp AR-M620 Europe	A1-98-53-2A	INVENDKIT3		
Sharp AR-M700	A1-98-53-2	DVENDDDG		
Sharp AR-M700 Europe	A1-98-53-2A	INVENDKIT3		
Sharp AR-N200	A1-98-53-2	DVENDPG		
Sharp AR-N200J	A1-98-53-2	DVENDPG		
Sharp AR-N205	A1-98-53-2	DVENDPG		
Sharp AR-N205J	A1-98-53-2	DVENDPG		
Sharp AR-P350	A1-98-53-2	DVENDTG		
Sharp AR-P450	A1-98-53-2	DVENDTG		
Sharp DM-3500	A1-98-53-2	DVENDTG		
Sharp DM-4500	A1-98-53-2	DVENDTG		
Sharp DM-4551		?		
Sharp MX-2300 Europe	A1-98-53-2A	INVENDKIT5		
Sharp MX-2300N	A1-98-53-2A	DVENDPS		
Sharp MX-2700 Europe	A1-98-53-2A	INVENDKIT5		
Sharp MX-2700N	A1-98-53-2A	DVENDPS		
Sharp MX-3500 Europe	A1-98-53-2A	INVENDKIT5		
Sharp MX-3500N	A1-98-53-2A	DVENDPS		
Sharp MX-3501 Europe	A1-98-53-2A	INVENDKIT5		
Sharp MX-3501N	A1-98-53-2A	DVENDPS	AD7-98-53-2A	DVENDPS
Sharp MX-4100N	A1-98-53-2A	DVENDPS		
Sharp MX-4101N	A1-98-53-2A	DVENDPS		
Sharp MX-4500 Europe	A1-98-53-2A	INVENDKIT5		
Sharp MX-4501 Europe	A1-98-53-2A	INVENDKIT5		
Sharp MX-4501N	A1-98-53-2A	DVENDPS		
Sharp MX-5001N	A1-98-53-2A		AD7-98-53-2A	
Sharp MX-5500 Europe	A1-98-53-2A	INVENDKIT5		
Sharp MX-5500N	A1-98-53-2A	DVENDPS		
Sharp MX-6200 Europe	A1-98-53-2A	INVENDKIT5		
Sharp MX-6200N	A1-98-53-2A	DVENDPS		
Sharp MX-6201N	A1-98-53-2A	DVENDPS		
Sharp MX-7000 Europe	A1-98-53-2A	INVENDKIT5		
Sharp MX-7000N	A1-98-53-2A	DVENDPS		
Sharp MX-7001N	A1-98-53-2A	DVENDPS		
Sharp MX-M1100	A1-98-53-2A	DVENDPS - as of 11/7/07, disables auto paper select, mixed size originals, adding a job - scan ahead, proof copy; firmware updates expected		
Sharp MX-M350N	A1-98-53-2A	DVENDTG		
Sharp MX-M363N	A1-98-53-2A		AD7-98-53-2A	
Sharp MX-M450N	A1-98-53-2A	DVENDTG	AD7-98-53-2A	
Sharp MX-M550	A1-98-53-2A	DVENDDDG		
Sharp MX-M620	A1-98-53-2A	DVENDDDG		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopyAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Sharp MX-M700	A1-98-53-2A	DVENDDG		
Sharp MX-M700N	A1-98-53-2A	DVENDTG	AD7-98-53-2A	DVENDTG
Sharp MX-M850	A1-98-53-2A	DVENDPS - as of 11/7/07, disables auto paper select, mixed size originals, adding a job - scan ahead, proof copy; firmware updates expected		
Sharp MX-M950	A1-98-53-2A	DVENDPS - as of 11/7/07, disables auto paper select, mixed size originals, adding a job - scan ahead, proof copy; firmware updates expected	AD7-98-53-2A	
Toshiba 2060	A1-98-13	Requires harness kit		
Toshiba 2330	A1-98-13	Harness built into copier		
Toshiba 2520	A1-98-13	Harness built into copier		
Toshiba 2570	A1-98-13	Harness built into copier		
Toshiba 3580	A1-98-13	Harness built into copier		
Toshiba 4550	A1-98-13	Harness built into copier		
Toshiba 4580	A1-98-13	Harness built into copier		
Toshiba 5010	A1-98-13	Harness built into copier		
Toshiba 5020	A1-98-13	Harness built into copier		
Toshiba 5511	A1-98-13	Harness built into copier		
Toshiba 5540	A1-98-13	Harness built into copier		
Toshiba 5560	A1-98-13	Harness built into copier		
Toshiba 5570	A1-98-13	Harness built into copier		
Toshiba 65	A1-98-13	Harness built into copier		
Toshiba 6550	A1-98-13	Harness built into copier		
Toshiba 6570	A1-98-13	Harness built into copier		
Toshiba 7110	No interface capability	Harness built into copier		
Toshiba 7501	A1-98-13	Harness built into copier		
Toshiba 7511	A1-98-13	Harness built into copier		
Toshiba 7560	A1-98-13	Requires harness kit		
Toshiba 7812	A1-98-13	Harness built into copier		
Toshiba 8070	A1-98-13	Harness built into copier		
Toshiba 8101	A1-98-13	Harness built into copier		
Toshiba 8102	A1-98-13	Harness built into copier		
Toshiba 8103	No interface capability	Harness built into copier		
Toshiba 8510	A1-98-13	Harness built into copier		
Toshiba 8812	A1-98-13	Harness built into copier		
Toshiba 2860	A1-98-13	Harness built into copier		
Toshiba 3580	A1-98-13	Harness built into copier		
Toshiba 9240	A1-98-13	Harness built into copier		
Toshiba DP1610	A1-98-13	Harness built into copier		
Toshiba DP2010	A1-98-13	Harness built into copier		
Toshiba DP2510	A1-98-13	Harness built into copier		
Toshiba DP3511	A1-98-13	Harness built into copier		
Toshiba DP3580	A1-98-13	Harness built into copier		
Toshiba DP4511	A1-98-13	Harness built into copier		

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Toshiba DP4520	A1-98-13	Harness built into copier		
Toshiba Estudio 2100C	A1-98-13	Harness built into copier		
Toshiba Estudio 3100C	A1-98-13	Harness built into copier		
Toshiba Estudio 1050	A1-98-07	Requires Ricoh-supplied harness kit A5095100		
Toshiba Estudio 1101	A1-98-07	Requires Ricoh harness A5095100		
Toshiba Estudio 1351	A1-98-07	Requires Ricoh harness A5095100		
Toshiba Estudio 16, 20	A1-98-13	requires harness from Toshiba 41309039000; If manufactured prior to 8/02, requires PWA boards		
Toshiba Estudio 160	A1-98-13	requires harness from Toshiba 41309039000; If manufactured prior to 8/02, requires PWA boards		
Toshiba Estudio 200	A1-98-13	requires harness from Toshiba 41309039000; If manufactured prior to 8/02, requires PWA boards		
Toshiba Estudio 200L	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 202L	A1-98-13	requires Toshiba harness 6LE8845000 HRNS-LGC-CTR 377S	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 203L	A1-98-13	requires Toshiba harness 6LE8845000 HRNS-LGC-CTR 377S	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 205L	A1-98-13	requires Toshiba harness 6LH60419000 ASYB-PACK-HRNS-KCTR	AD7-98-13	requires Toshiba harness 6LH60419000 ASYB-PACK-HRNS-KCTR
Toshiba Estudio 211C	A1-98-13	Harness built into copier		
Toshiba Estudio 230	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 232	A1-98-13	requires Toshiba harness 6LE8845000 HRNS-LGC-CTR 377S	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 2330C	A1-98-13	requires Toshiba harness 6LE27469000 KIT KEYCOUNTER-380S	AD7-98-13-GQ	GQ-1110
Toshiba Estudio 250	A1-98-13	requires harness from Toshiba 41309039000; If manufactured prior to 8/02, requires PWA boards		
Toshiba Estudio 2500C	A1-98-13	requires Toshiba harness 6LE27469000 Kit-Key-Counter 380S	AD7-98-13-GQ	GQ-1110
Toshiba Estudio 255	A1-98-13	requires Toshiba harness 6LH60419000 ASYB-PACK-HRNS-KCTR	AD7-98-13	requires Toshiba harness 6LH60419000 ASYB-PACK-HRNS-KCTR
Toshiba Estudio 25S	A1-98-13	Harness built into copier		
Toshiba Estudio 28	A1-98-13	Harness built into copier		
Toshiba Estudio 280	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1020

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Toshiba Estudio 281C	A1-98-13	Requires Toshiba harness 6LE48068000 HRNS-LGC-COUNTER-410S	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 282	A1-98-13	requires Toshiba harness 6LE8845000 HRNS-LGC-CTR 377S	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 2820C	A1-98-13	requires Toshiba harness 6LE27469000 KIT KEYCOUNTER-380S	AD7-98-13-GQ	GQ-1110
Toshiba Estudio 2830C	A1-98-13	requires Toshiba harness 6LE27469000 KIT KEYCOUNTER-380S	AD7-98-13-GQ	GQ-1110
Toshiba Estudio 305	A1-98-13	requires Toshiba harness 6LH60419000 ASYB-PACK-HRNS-KCTR	AD7-98-13	requires Toshiba harness 6LH60419000 ASYB-PACK-HRNS-KCTR
Toshiba Estudio 35	A1-98-13	Harness built into copier		
Toshiba Estudio 350	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 3500C	A1-98-13	requires Toshiba harness 6LE27469000 Kit-Key-Counter 380S	AD7-98-13-GQ	GQ-1110
Toshiba Estudio 3510C	A1-98-13	requires Toshiba harness 6LE27469000 Kit-Key-Counter 380S	AD7-98-13-GQ	GQ-1110
Toshiba Estudio 3511	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 351C	A1-98-13	Requires Toshiba harness 6LE48068000 HRNS-LGC-COUNTER-410S	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 352	A1-98-13	Requires Toshiba harness 6LE83250000 HRNS-LGC-CTR-364S	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 3520C	A1-98-13	requires Toshiba harness 6LE27469000 KIT KEYCOUNTER-380S	AD7-98-13-GQ	GQ-1110
Toshiba Estudio 353	A1-98-13	Requires Toshiba harness 6LE83250000 HRNS-LGC-CTR-364S	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 3530C	A1-98-13	requires Toshiba harness 6LE27469000 KIT KEYCOUNTER-380S	AD7-98-13-GQ	GQ-1110
Toshiba Estudio 355	A1-98-13	requires Toshiba harness 6LH60419000 ASYB-PACK-HRNS-KCTR	AD7-98-13	requires Toshiba harness 6LH60419000 ASYB-PACK-HRNS-KCTR
Toshiba Estudio 45	A1-98-13	Harness built into copier		
Toshiba Estudio 450	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 4500C	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Ricoh supplied 413012
Toshiba Estudio 4511	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1020

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Toshiba Estudio 451C	A1-98-13	Requires Toshiba harness 6LE48068000 HRNS-LGC-COUNTER-410S	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 452	A1-98-13	Requires Toshiba harness 6LE83250000 HRNS-LGC-CTR-364S	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 4520C	A1-98-13	requires Toshiba harness 6LE27469000 KIT KEYCOUNTER-380S	AD7-98-13-GQ	GQ-1110
Toshiba Estudio 453	A1-98-13	Requires harness 6LE83250000 HRN	AD7-98-13-GQ	GQ-1020
Toshiba Estudio 455	A1-98-13	requires Toshiba harness 6LH60419000 ASYB-PACK-HRNS-KCTR	AD7-98-13	requires Toshiba harness 6LH60419000 ASYB-PACK-HRNS-KCTR
Toshiba Estudio 520	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1040
Toshiba Estudio 523	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1040
Toshiba Estudio 55	A1-98-13	Harness built into copier		
Toshiba Estudio 550	A1-98-13	Harness built into copier		
Toshiba Estudio 5500C	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	Ricoh supplied 413012
Toshiba Estudio 5520C	A1-98-13	requires Toshiba harness 6LH09467000 HRNS-LGC-CTR-430	AD7-98-13-GQ	GQ-1200
Toshiba Estudio 555	A1-98-13	4 pin harness included in copier: 6LE09278000 HRNS-LGC-DEVM-390	AD7-98-13	4 pin harness included in copier: 6LE09278000 HRNS-LGC-DEVM-390
Toshiba Estudio 600	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1040
Toshiba Estudio 600T	A1-98-13	Harness built into copier		
Toshiba Estudio 603	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1040
Toshiba Estudio 65	A1-98-13	Harness built into copier		
Toshiba Estudio 650	A1-98-13	Harness built into copier		
Toshiba Estudio 6520C	A1-98-13	requires Toshiba harness 6LH09467000 HRNS-LGC-CTR-430	AD7-98-13-GQ	GQ-1200
Toshiba Estudio 6530C	A1-98-13	requires Toshiba harness 6LH09467000 HRNS-LGC-CTR-430	AD7-98-13-GQ	GQ-1200
Toshiba Estudio 655	A1-98-13	4 pin harness included in copier: 6LE09278000 HRNS-LGC-DEVM-390	AD7-98-13	4 pin harness included in copier: 6LE09278000 HRNS-LGC-DEVM-390
Toshiba Estudio 720	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1040
Toshiba Estudio 723	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1040
Toshiba Estudio 755	A1-98-13	4 pin harness included in copier: 6LE09278000 HRNS-LGC-DEVM-390	AD7-98-13	4 pin harness included in copier: 6LE09278000 HRNS-LGC-DEVM-390
Toshiba Estudio 810	A1-98-13	Harness built into copier		
Toshiba Estudio 850	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1040
Toshiba Estudio 853	A1-98-13	Harness built into copier	AD7-98-13-GQ	GQ-1040
Toshiba Estudio 855	A1-98-13	4 pin harness included in copier: 6LE09278000 HRNS-LGC-DEVM-390	AD7-98-13	4 pin harness included in copier: 6LE09278000 HRNS-LGC-DEVM-390

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Toshiba Estudio 900	A1-98-07	Requires Ricoh-supplied harness kit A5095100	AD7-98-07-20	
Toshiba Estudio 901	A1-98-07	Requires Ricoh harness A5095100		
Xerox 1010DC	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 1010FI. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 1010FI. Requires BEAR Kit.
Xerox 2101DC	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 1010FI. Requires BEAR Kit.	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 1010FI. Requires BEAR Kit.
Xerox 4110	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE . Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE . Requires BEAR Kit.
Xerox 4112	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE 2. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE 2. Requires BEAR Kit.
Xerox 4127	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE 2. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE 2. Requires BEAR Kit.
Xerox 4590	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE . Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE . Requires BEAR Kit.
Xerox 4595	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE . Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE . Requires BEAR Kit.
Xerox 5337	A1-98-49	Requires Xerox-supplied Foreign Interface Harness kit 98K16286 plus accessory pod 5352POD	AD7-98-45	
Xerox 5340	A1-98-49	Requires Xerox-supplied Foreign Interface Harness kit 98K16285 plus accessory pod 98K32670	AD7-98-45	
Xerox 5342	A1-98-49	Requires Xerox-supplied Foreign Interface Harness kit	AD7-98-45	
Xerox 5343	A1-98-49	Requires Xerox-supplied Foreign Interface Harness kit 98K16286 plus accessory pod 98K32672	AD7-98-45	
Xerox 5350	A1-98-49	Requires Xerox-supplied Foreign Interface Harness kit 98K16285 plus accessory pod 98K32670	AD7-98-45	
Xerox 5352	A1-98-49	Requires Xerox-supplied Foreign Interface Harness kit 98K16286 plus accessory pod 98K32672	AD7-98-45	

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Xerox 5352C	A1-98-49	Requires Xerox-supplied Foreign Interface Harness kit 98K16286 plus accessory pod 98K32672	AD7-98-45	
Xerox 5355	A1-98-50	Requires Xerox-supplied Foreign Interface Harness kit 98K65330	AD7-98-45	
Xerox 5365	A1-98-49	Interface Board Built-in	AD7-98-45	
Xerox 5380	A1-98-50	Interface Board Built-in	AD7-98-45	
Xerox 5385	A1-98-49	Interface Board Built-in	AD7-98-45	
Xerox 5388	A1-98-49	Requires Xerox-supplied Foreign Interface Harness kit 98S610	AD7-98-45	
Xerox 5400	A1-98-50	Requires Xerox-supplied Foreign Interface Harness kit	AD7-98-45	
Xerox 5600	A1-98-04	Requires Xerox-supplied Foreign Interface Harness kit	AD7-98-45	
Xerox 5614	A1-98-49	Requires Xerox-supplied Foreign Interface Harness kit 98K26400	AD7-98-45	
Xerox 5665	A1-98-49	Requires Xerox-supplied Foreign Interface Harness kit 98K16286 plus accessory pod 98K32671	AD7-98-45	
Xerox 5680	A1-98-49	Requires Xerox-supplied Foreign Interface Harness kit 98S610	AD7-98-45	
Xerox 5830	A1-98-49	Requires Xerox-supplied Foreign Interface Harness kit 98K20912	AD7-98-45	
Xerox 5837	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K16287 plus Accessory pod 98K32672	AD7-98-45	
Xerox 5845	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K16287 plus Accessory pod 98K32672	AD7-98-45	
Xerox 5855C	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K16287 plus Accessory pod 98K32672	AD7-98-45	
Xerox 5885	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K32500	AD7-98-45	
Xerox 700 Digital Color Press	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDEVICE 2. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDEVICE 2. Requires BEAR Kit.
Xerox CC 65	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80Fi.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80Fi.
Xerox CC 75	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80Fi.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80Fi.
Xerox CC 90	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80Fi.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80Fi.
Xerox CC C123	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28Fi. Requires BEAR kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28Fi. Requires BEAR kit.

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Xerox CC C128	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI. Requires BEAR kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI. Requires BEAR kit.
Xerox CC C133	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI. Requires BEAR kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI. Requires BEAR kit.
Xerox CCC55	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit	A1-98-45	
Xerox ColorQube 9201	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code CQFIDKIT	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code CQFIDKIT
Xerox ColorQube 9202	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code CQFIDKIT	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code CQFIDKIT
Xerox ColorQube 9203	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code CQFIDKIT	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code CQFIDKIT
Xerox DC12	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.
Xerox DC1632	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.
Xerox DC212	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K65090	AD7-98-45	
Xerox DC214	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K65090	AD7-98-45	
Xerox DC220	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98S3031	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98S3031
Xerox DC2240	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.
Xerox DC230	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98S3031	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98S3031
Xerox DC255	A1-98-45	Xerox-supplied Foreign Interface Harness kit built in.	AD7-98-45	Xerox-supplied Foreign Interface Harness kit built in.
Xerox DC265	A1-98-45	Xerox-supplied Foreign Interface Harness kit built in.	AD7-98-45	Xerox-supplied Foreign Interface Harness kit built in.
Xerox DC332	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K81521	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K81521
Xerox DC340	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K81521	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K81521

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Xerox DC3535	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.
Xerox DC420	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC220FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC220FI
Xerox DC423	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit	AD7-98-45	
Xerox DC425	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC32FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC32FI
Xerox DC426	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC32FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC32FI
Xerox DC430	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC32FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC32FI
Xerox DC432	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC32FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC32FI
Xerox DC440	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC32FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC32FI
Xerox DC460	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI
Xerox DC470	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI
Xerox DC480	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI
Xerox DC490	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI
Xerox DC535	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC35FI and Vendor Adaptor	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC35FI and Vendor Adaptor
Xerox DC545	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC35FI and Vendor Adaptor	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC35FI and Vendor Adaptor
Xerox DC550C	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI	AD7-98-45	
Xerox DC555	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC35FI and Vendor Adaptor	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC35FI and Vendor Adaptor
Xerox DCCS50	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit. Requires BEAR Kit.
Xerox DocuCenter 240	A1-98-45	Xerox-supplied Foreign Interface Harness kit built in.	AD7-98-45	Xerox-supplied Foreign Interface Harness kit built in.
Xerox DocuColor 2000	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requires BEAR Kit.

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Xerox DocuColor 2045	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requires BEAR Kit.
Xerox DocuColor 2060	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requires BEAR Kit.
Xerox DocuColor 240	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.
Xerox DocuColor 242	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE 2. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE 2. Requires BEAR Kit.
Xerox DocuColor 250	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.
Xerox DocuColor 252	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE 2. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE 2. Requires BEAR Kit.
Xerox DocuColor 260	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE 2. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE 2. Requires BEAR Kit.
Xerox DocuColor 5000 AP Digital C	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requirse BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requirse BEAR Kit.
Xerox DocuColor 5252	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requirse BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requirse BEAR Kit.
Xerox DocuColor 6060	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requirse BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requirse BEAR Kit.
Xerox DocuColor 7000	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requirse BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requirse BEAR Kit.
Xerox DocuColor 8000	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requirse BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code GWF. Requirse BEAR Kit.
Xerox DocuTech	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K7820	AD7-98-45	
Xerox DocuTech 135	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K7820	AD7-98-45	
Xerox DocuTech 6155	NA	No interface available	NA	

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Xerox Phaser 3635 MFP	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit . Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit . Requires BEAR Kit.
Xerox WC 4118	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 20 FI. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 20 FI. Requires BEAR Kit.
Xerox WC 4150	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 20 FI. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 20 FI. Requires BEAR Kit.
Xerox WC 4250	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit MXR. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit MXR. Requires BEAR Kit.
Xerox WC 4260	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit MXR. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit MXR. Requires BEAR Kit.
Xerox WC 5222	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDKIT. Requires BEAR Kit	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDKIT. Requires BEAR Kit
Xerox WC 5225	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDKIT. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDKIT. Requires BEAR Kit.
Xerox WC M15	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit CAS #M15-01. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit CAS #M15-01. Requires BEAR Kit.
Xerox WC M15i	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit CAS #M15-01. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit CAS #M15-01. Requires BEAR Kit.
Xerox WC M20	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 20 FI. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 20 FI. Requires BEAR Kit.
Xerox WC M20i	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 20 FI. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 20 FI. Requires BEAR Kit.
Xerox WC M24	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE. Requires BEAR Kit.
Xerox WC5030	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - 200FI	AD7-98-45	
Xerox WC5632	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI
Xerox WC5632 - with TAG 40	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit WC56FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit WC56FI
Xerox WC5638	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI
Xerox WC5638 - with TAG 40	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit WC56FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit WC56FI

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Xerox WC5655	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI
Xerox WC5655 - with TAG 40	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit WC56FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit WC56FI
Xerox WC5675	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI
Xerox WC5687	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI
Xerox WC7132	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.
Xerox WC7228EUR	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 498K14141. Require BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 498K14141. Requirse BEAR Kit.
Xerox WC7232	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.
Xerox WC7235EUR	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 498K14141. Require BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 498K14141. Requirse BEAR Kit.
Xerox WC7242	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.
Xerox WC7245EUR	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 498K14141. Require BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 498K14141. Requirse BEAR Kit.
Xerox WC7328	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.
Xerox WC7335	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.
Xerox WC7345	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.
Xerox WC7346	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.
Xerox WC7425	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.
Xerox WC7428	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.
Xerox WC7435	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit FIDKIT. Requires BEAR Kit.

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Xerox WC7655	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit YRC.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit YRC.
Xerox WC7665	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit YRC.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit YRC.
Xerox WC7675	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit YRC.	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit YRC.
Xerox WC7755	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit .	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit .
Xerox WC7765	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit .	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit .
Xerox WC7775	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit .	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit .
Xerox WCM123	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI and BEAR kit	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI and BEAR kit
Xerox WCM128	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI and BEAR kit	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI and BEAR kit
Xerox WCM133	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI and BEAR kit	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI and BEAR kit
Xerox WCM24	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code FIDEVICE
Xerox WCP 123	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI
Xerox WCP 128	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI
Xerox WCP 133	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit - Market Code 23-28FI
Xerox WCP232	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit	AD7-98-45	
Xerox WCP32	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit NCN	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit NCN
Xerox WCP35	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC35FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC35FI
Xerox WCP40	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit NCN	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit NCN
Xerox WCP45	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC35FI	AD7-98-45	
Xerox WCP55	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC35FI	AD7-98-45	
Xerox WC5645	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopvAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Xerox WC5645 - with TAG 40	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit WC56FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit WC56FI
Xerox WCP65	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI
Xerox WCP75	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI
Xerox WCP90	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC80FI
Xerox WCPC2128	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98S4822	AD7-98-45	
Xerox WCPC2636	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98S4822	AD7-98-45	
Xerox WCPC3545	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98S4822	AD7-98-45	
Xerox WCPS32	A1-98-45	N/A, specification due for publication by Xerox	AD7-98-45	
Xerox WCPS40	A1-98-45	N/A, specification due for publication by Xerox	AD7-98-45	
Xerox XC33D	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit
Xerox CopyCentre 35/45/55	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 35FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 35FI
Xerox CopyCentre 232/238	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI
Xerox CopyCentre 245/255	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI
Xerox CopyCentre 265/275	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI
Xerox CopyCentre C165/175	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 65FID	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 65FID
Xerox WorkCentre 232/238/245/255	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI
Xerox WorkCentre 5030/5050	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 35FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 35FI
Xerox WorkCentre 5135/5150	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 35FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 35FI
Xerox WorkCentre M35/M45/M55	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC35FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit DC35FI
Xerox WorkCentre Pro 35/45/55	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI
Xerox WorkCentre Pro 165/175	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 65FID	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 65FID
Xerox WorkCentre Pro 232/238	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI
Xerox WorkCentre Pro 245/255/265	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI

# Transaction Recovery Systems, Inc

Copier Make/Model	TRS Copier Cable for ADD4/CopyAudit	Copier Vendor-supplied harness kit for ADD4/Copy Audit	TRS Copier Cable for Copy Audit Touch	Copier Vendor-supplied harness kit for Copy Audit Touch
Xerox WorkCentre Bookmark 40/50	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 200FI
Xerox CopyCentre 32/40	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit NCN	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit NCN
Xerox CopyCentre C2128	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit TNV	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit TNV
Xerox CopyCentre C2636	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit TNV	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit TNV
Xerox CopyCentre C3545	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit TNV	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit TNV
Xerox WorkCentre Pro C2128	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit TNV	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit TNV
Xerox WorkCentre Pro C2636	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit TNV	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit TNV
Xerox WorkCentre Pro C3545	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit TNV	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit TNV
Xerox 5750	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98S1905	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98S1905
Xerox 5760/5765	A1-98-45	Harness built in	AD7-98-45	Harness built in
Xerox 5775	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K14451	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98K14451
Xerox 5790	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98S33340	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98S33340
Xerox 5799	A1-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98S1906	AD7-98-45	Requires Xerox-supplied Foreign Interface Harness kit 98S1906